

## Wills House Photo Log



MSU Wills House

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #1 – Asbestos-containing steam and condensate supply and return pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #2 – Asbestos-containing steam and condensate supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #3 – Asbestos-containing smooth wall and ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #4 – Asbestos-containing dark brown glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #5 – Non asbestos-containing window glazing caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #6 – Asbestos-containing 9” x 9” tan floor tile with cream and tan streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #7 – Asbestos-containing brown linoleum with cream and black streaks and associated non asbestos containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #8 – Non asbestos-containing dark green linoleum and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #9 – Asbestos-containing domestic water supply pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #10 – Asbestos-containing domestic water supply pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #11 – Non asbestos-containing white textured ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #12 – Non asbestos-containing 2' x 2' white lay-in ceiling tile  
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #13 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #14 – Non asbestos-containing 4” black cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Wills House Photo Log



HA #16 – Non asbestos-containing 12” x 12” white ceiling tile with fissures and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956