

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-01 Non-asbestos containing green linoleum with marble pattern and associated mastic




HA-02 Non-asbestos containing 4" black cove molding and associated mastic.

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan




HA-03 Non-asbestos containing white textured wall plaster



HA-04 Non-asbestos containing white smooth ceiling plaster

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-05 Non-asbestos containing green square pattern linoleum stair tread flooring and associated mastic



HA-06 Assumed asbestos-containing ceramic floor tile bedding compound and grout

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-07 Assumed asbestos-containing ceramic wall tile bedding compound and grout



HA-08 Non-asbestos containing interior white window caulk

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-09 Non-asbestos containing white rough texture plaster



HA-10 Non-asbestos containing drywall

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan




HA-11 Non-asbestos containing drywall joint compound




HA-12 Non-asbestos containing fiberboard wall panels and associated mastic

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-13 Non-asbestos containing black mastic on floor



HA-14 Non-asbestos containing black linoleum and associated mastic

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-15 Non-asbestos containing yellow carpet mastic




HA-16 Non-asbestos containing 4" maroon cove molding and associated mastic

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan




HA-17 Non-asbestos containing white 12" x 12" glued-on ceiling tile with uniform holes and HA-18 Assumed asbestos-containing gluepods



HA-19 Non-asbestos containing green linoleum with texture and associated mastic

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-20 Non-asbestos containing gray sink undercoating

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-21 Non-asbestos containing interior light brown window sill caulk

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-22 Non-asbestos containing interior red brick caulk



HA-23 Asbestos containing exterior black waterproofing

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan




HA-24 Non-asbestos containing exterior brown building caulk



HA-25 Non-asbestos containing exterior gray front steps caulk

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-26 Non-asbestos containing exterior white window caulk



HA-27 Assumed asbestos-containing gray roof shingles and felts (tar paper)

Eustace-Cole Hall
468 East Circle Drive
East Lansing, Michigan



HA-28 Non-asbestos containing exterior white door caulk