

Kedzie Hall Photo Log



Exterior of Kedzie Hall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #1 – Non asbestos-containing smooth wall and ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #2 – Non asbestos-containing 2' x 4' white lay-in ceiling tile
with pin holes

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #3 – Asbestos-containing 9" x 9" gray floor tile with cream and rust streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #4 – Non asbestos-containing 4" black cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #5 – Non asbestos-containing 12" x 12" black floor tile
with white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #6 – Non asbestos-containing 6" brown cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #7 – Asbestos-containing tan stair tread with cream, pink and black streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kedzie Hall Photo Log



HA #8 – Asbestos-containing 9" x 9" tan floor tile with swirl pattern and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #9 – Assumed asbestos-containing chalkboards and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #10 – Non asbestos-containing 2' x 2' white lay-in ceiling tile
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #11 – Assumed asbestos-containing black laboratory tables and sinks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #12 – Non asbestos-containing green vinyl flooring with black and white specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #13 – Non asbestos-containing green linoleum flooring with white streaks and associated backing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #14 – Non asbestos-containing 12" x 12" cream floor tile
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #15 – Non asbestos-containing white sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #16 – Non asbestos-containing 12" x 12" tan linoleum
with small square pattern and associated backing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #17 – Non asbestos-containing 12" x 12" beige floor tile
with tan and white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #18 – Non asbestos-containing 12" x 12" cream floor tile
with black and tan streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #19 – Non asbestos-containing 12" x 12" white spline ceiling tile with fissures and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #20 – Non asbestos-containing fireboard
(behind 12" x 12" white spline ceiling tile)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #21 – Asbestos-containing tan linoleum with brown and white specks
and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #22 – Asbestos-containing tan stair tread with brown and white specks
and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #23 – Asbestos-containing 9" x 9" blue floor tile with white and black streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #24 – Asbestos-containing 9" x 9" green floor tile with white and green streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #25 – Non asbestos-containing 12" x 12" white floor tile with tan and gray marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #26 – Non asbestos-containing 4" tan cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #27 – Non asbestos-containing 4" gray cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #28 – Non asbestos-containing 4" brown cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #29 – Asbestos-containing steam/condensate supply and return pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #31 – Asbestos-containing 9" x 9" tan floor tile with cream and rust streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #32 – Asbestos-containing steam/condensate supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #35 – Asbestos-containing domestic water supply pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #36 – Non asbestos-containing 12" x 12" white floor tile
with black specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #37 – Non asbestos-containing 12" x 12" dark green floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #38 – Non asbestos-containing 12" x 12" pink marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #40 – Non asbestos-containing 12" x 12" blue marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #41 – Non asbestos-containing 2' x 2' white lay-in ceiling tile with texture

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #42 – Non asbestos-containing ventilation duct expansion cloth

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #43 – Non asbestos-containing 12" x 12" tan multi-colored marble pattern floor tile and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #44 – Non asbestos-containing light green vinyl stair tread
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kedzie Hall Photo Log



HA #46 – Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956