

River Water Research Laboratory Photo Log



Exterior of the River Water Research Building

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #1 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #3 – Non asbestos-containing 2' x 2' white lay-in ceiling tile with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #4 – Non asbestos-containing 4” brown cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #7 – Non asbestos-containing steam/condensate supply and return pipe straight insulation (fiberglass line/canvas cover)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #8 – Asbestos-containing steam/condensate supply and return pipe joint insulation (on fiberglass line)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #9 – Non asbestos-containing exterior window  
and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #10 – Assumed asbestos-containing laboratory fume hood

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #11 – Assumed asbestos-containing laboratory sinks,  
table tops and ledges

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #12 – Asbestos-containing black sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Laboratory Photo Log



HA #13 – Asbestos-containing building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956