


## River Water Research Center Photo Log



Exterior of the MSU River Water Research Building

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #1 – Asbestos-containing window and door frame caulk compound  
(interior)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #2 – Non asbestos-containing domestic water supply pipe joint insulation (on fiberglass pipe straight insulation)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #3 – Asbestos-containing window glazing compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #4 – Assumed asbestos-containing laboratory sinks and table tops

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #5 – Asbestos-containing transite heat vent pipe

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #6 – Assumed asbestos-containing laboratory fume hood

For more information contact MSU Environmental Health and Safety – (517) 353-8956



River Water Research Center Photo Log



HA #8 – Asbestos-containing window and door frame caulk compound  
(exterior)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

River Water Research Center Photo Log



HA #9 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956