

Demonstration Hall Photo Log



Non-asbestos containing tan linoleum with cream and brown streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 9" x 9" wood grain pattern floor tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 9" x 9" gray floor tile with cream and pink streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam pipe straight insulation ACM debris
on floor of tunnel area

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Non-asbestos containing plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 9" x 9" black floor tile with cream and green streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 9" x 9" black floor tile with cream streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Non-asbestos containing tan linoleum with cream and brown streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 9" x 9" tan floor tile with cream and rust streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing 1' x 2' brown floor tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing radiator backing paper

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Non-asbestos containing 6" brown cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Non-asbestos containing 12" x 12" tan floor tile with cream and rust streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Demonstration Hall Photo Log



Assumed asbestos-containing window glazing compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing raised platform ACM debris

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam pipe straight insulation ACM debris
on floor of tunnel area

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing hot water holding tank insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Damaged thermal system insulation, Boiler Room

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing Steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing boiler thermal system insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing sewer drain pipe straight insulation and asbestos-containing sewer drain pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing domestic water pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing steam/condensate pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Asbestos-containing domestic water pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Assumed asbestos-containing window and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Assumed asbestos-containing window glazing compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Outside of building, Demonstration Hall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Assumed asbestos-containing window and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Demonstration Hall Photo Log



Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956