

Bessey Hall Photo Log



HA #1 – Non asbestos-containing spray-on fireproofing

Bessey Hall Photo Log



HA #6 – Non asbestos-containing 12” x 12” white ceiling tile
with pin holes and associated glue pods

Bessey Hall Photo Log




HA #7 – Non asbestos-containing 4” light brown cove molding
and associated mastic

Bessey Hall Photo Log



HA #8 – Non asbestos-containing 4” dark brown
cove molding and associated mastic

Bessey Hall Photo Log



HA #9 – Non asbestos-containing 4” black cove molding
and associated mastic

Bessey Hall Photo Log



HA #10 – Non asbestos-containing tan vinyl flooring
with blue specks and associated mastic

Bessey Hall Photo Log



HA #11 – Non asbestos-containing 12” x 12” tan floor tile with marble pattern and associated asbestos-containing mastic

Bessey Hall Photo Log



HA #12 – Non asbestos-containing 12” x 12” cream floor tile with white and green streaks and associated asbestos-containing mastic

Bessey Hall Photo Log



HA #13 – Non asbestos-containing brown linoleum flooring with rust streaks and associated mastic

Bessey Hall Photo Log



HA #14 – Non asbestos-containing brown stair tread with cream, pink and black streaks and associated mastic

Bessey Hall Photo Log



HA #15 – Non asbestos-containing gray stair tread
with cream streaks and associated mastic

Bessey Hall Photo Log



HA #19 – Asbestos-containing steam/condensate supply and return pipe straight insulation

Bessey Hall Photo Log



HA #21 – Asbestos-containing domestic water supply
pipe joint and hanger insulation

Bessey Hall Photo Log



HA #22 – Asbestos-containing hot water heating expansion tank insulation

Bessey Hall Photo Log



HA #23 – Assumed asbestos-containing chalkboards
and associated glue pods

Bessey Hall Photo Log



HA #24 – Assumed asbestos-containing building caulk compound

Bessey Hall Photo Log



HA #26 – Assumed asbestos-containing window and door frame caulk compound

Bessey Hall Photo Log



HA #27 – Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Bessey Hall Photo Log



HA #28 – Non asbestos-containing ceramic tile bedding compound

Bessey Hall Photo Log



HA #29 – Non asbestos-containing 9” x 9” dark brown floor tile
with cream and rust streaks and associated mastic

Bessey Hall Photo Log



HA #30 – Non asbestos-containing 2' x 4' white lay-in ceiling tile with pin holes

Bessey Hall Photo Log




HA #32 – Non asbestos-containing 12” x 12” white spline ceiling tile with pin holes and fissures and associated glue pods

Bessey Hall Photo Log



HA #33 – Non asbestos-containing gray pipe chase mud packing compound

Bessey Hall Photo Log



HA #36 – Non asbestos containing 12” x 12” blue floor tile with marble pattern and associated asbestos-containing mastic

Bessey Hall Photo Log



HA #37 – Non asbestos-containing 12” x 12” dark gray floor tile with marble pattern and associated asbestos-containing mastic

Bessey Hall Photo Log



HA #38 – Non asbestos-containing white sink undercoating.

Bessey Hall Photo Log



HA #40 – Asbestos-containing light heat shield insulation

Bessey Hall Photo Log



HA #41 – Non asbestos-containing 4” gray cove molding
and associated mastic

Bessey Hall Photo Log



HA #42 – Assumed asbestos-containing gray slate caulk compound