



Physical Plant Photo Log



HA #1 – Non asbestos-containing cream textured ceiling and wall paint

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Physical Plant Photo Log



HA #2 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #4 – Non asbestos-containing 2' x 2' white lay-in ceiling tile
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #6 – Non asbestos-containing 12" x 12" white ceiling tile with deep fissures and pin holes and non asbestos containing associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #7 – Non asbestos-containing 4" green cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #8 – Non asbestos-containing 4" dark brown cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #9 – Non asbestos-containing 4" gray cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #10 – Non asbestos-containing 4" black cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #12 – Asbestos-containing 9" x 9" tan floor with cream and rust streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Physical Plant Photo Log



HA #13 – Asbestos-containing 9" x 9" beige floor tile with light and dark brown swirl pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #14 – Non asbestos-containing 9" x 9" pink floor tile with cream and brown specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #15 – Non asbestos-containing 12" x 12" white floor tile with dark gray and white swirl pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #16 – Non asbestos-containing 12" x 12" light brown floor tile with cream and rust streaks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #17 – Non asbestos-containing 12" x 12" tan floor tile with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #18 – Non asbestos-containing 12" x 12" green floor tile
with white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Physical Plant Photo Log



HA #19 – Non asbestos-containing 12" x 12" white floor tile with white and tan streaks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #20 – Non asbestos-containing 12" x 12" white floor tile
with gray streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #21 – Non asbestos-containing dark brown vinyl stair tread
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #22 – Asbestos-containing orange vinyl stair tread with white and black streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #23 – Non asbestos-containing gray sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #33 – Asbestos-containing 9” x 9” gray floor tile with pink and cream streaks and non asbestos containing associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #34 – Non asbestos-containing 12" x 12" white spline ceiling tile with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #35 – Asbestos-containing 9" x 9" gray floor tile with swirl pattern and associated asbestos-containing mastic

HA #36 – Non asbestos-containing 9" x 9" tan floor tile with cream streaks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



Exterior of the Physical Plant Building

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #26 – Non asbestos containing building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Physical Plant Photo Log



HA #25 – Asbestos containing tan window and door frame
caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956