



Photo 28 – Window caulk (outside), east side of building



Photo 29 – Baker Hall, exterior of building, facing northeast



Photo 30 – 5th floor, ceiling plenum access area,
facing east from southwest corner



Photo 31 – Fire protection ceiling board in 5th floor ceiling access area




Photo 32 – Roof flashing



Photo 33 – Roof flashing




Photo 34 – Room 50A, electrical cable wrap




Photo 17 – Plaster, cove molding and vinyl wall covering, 1st floor, hallway, south wall, facing Room 153A



Photo 18 – Fire door, southwest landing to 1st floor entrance



Photo 19 – Mechanical Room 50, silver treated pipe joint insulation



Photo 20 – Mechanical room 50, maroon high pressure steam pipe straight insulation and pipe joint insulation, southwest of tunnel access




Photo 21 – Mechanical room 50, gray low pressure steam pipe joint insulation, southeast of condensate tank



Photo 22 - Mechanical room 50, white chilled water pipe joint insulation, northeast of tunnel entrance




Photo 23 – Ceiling insulation (tectum board), Room 146



Photo 24 – Black vinyl stair tread with white streaks, southwest stairwell



Photo 25 – Window caulk (inside),
northeast landing of 1st floor, facing south




Photo 26 – Door frame caulk (inside), northeast entrance area




Photo 27 – Door frame caulk (outside), northeast entrance area