

Life Sciences Photo Log



HA #1 – Asbestos-containing spray-on fireproofing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #4 – Non asbestos-containing plaster (smooth)

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #5 – Asbestos-containing steam/condensate supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #7 – Asbestos-containing 1' x 2' gray floor tile with cream streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #8 – Asbestos-containing 9” x 9” gray floor tile with cream and gray streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #9 – Non asbestos-containing 4” cream cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #10 – Non asbestos-containing gray sink undercoating insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #11 – Non asbestos-containing 4” brown cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #12 – Non asbestos-containing 12” x 12” light blue floor tile with marble pattern and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #13 – Asbestos-containing 9” x 9” green floor tile with cream and black streaks and associated mastic


For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #14 – Assumed asbestos-containing black laboratory sink and table tops

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #15 – Assumed asbestos-containing chalkboards and associated glue pods



HA #16 – Non asbestos-containing 12” x 12” gray floor tile with white streaks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #17 – Non asbestos-containing tan linoleum with mosaic pattern
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #19 – Asbestos-containing 12” x 12” tan floor tile with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #21 – Non asbestos-containing 12” x 12” tan floor tile with cream and brown streaks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #23 – Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #25 – Non asbestos-containing 4” black cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #26 – Non asbestos-containing 4” white cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #27 – Asbestos-containing 9” x 9” cream floor tile with dark brown streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #28 – Non asbestos-containing 12” x 12” brown floor tile with marble pattern and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #30 – Assumed asbestos-containing window
and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #30 – Assumed asbestos-containing window
and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #33 – Asbestos-containing 9” x 9” sea-foam green floor tile with swirls and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #37 – Non asbestos-containing 9” x 9” cream floor tile with black streaks and associated asbestos-containing mastic



HA #39 – Non asbestos-containing 12” x 12” white floor tile with mosaic pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #40 – Non asbestos-containing white sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #41 – Non asbestos-containing 4” gray cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #42 – Non asbestos-containing 2' x 2' white lay-in ceiling tile
with pin holes

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #44 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



HA #45 – Assumed asbestos-containing black slate window sill

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #46 – Non asbestos-containing 4” tan cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #47 – Non asbestos-containing 12” x 12” white spline ceiling tile
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #49 – Asbestos-containing drain system pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #54 – Non asbestos-containing trowelled-on fireproofing

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #56 – Asbestos-containing tan stair tread with cream, black and pink streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #57 – Asbestos-containing canvas wrap on fiberglass insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #58 – Non asbestos-containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #58 – Non asbestos-containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Life Sciences Photo Log



Exterior of Life Science Building

For more information contact MSU Environmental Health and Safety – (517) 353-8956