


## Amtrak Station Photo Log



Amtrak Station, East Lansing, Michigan

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #1 – Asbestos-containing 9" x 9" gray floor tile with white streaks  
and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #2 – Non asbestos-containing 4" black cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Amtrak Station Photo Log




HA #3 – Non asbestos-containing drywall

HA #4 – Asbestos-containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #5 – Non asbestos-containing 12" x 12" gray floor tile with gray and white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #6 – Non asbestos-containing 12" x 12" white floor tile  
with brown and gray streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #7 – Non asbestos-containing 6" gray cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #8 – Assumed asbestos-containing safe

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Amtrak Station Photo Log



HA #9 – Non asbestos-containing textured ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #10 – Assumed asbestos-containing ceramic tile bedding compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #11 – Asbestos-containing black sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #12 – Non asbestos-containing 6” black cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Amtrak Station Photo Log



HA #13 – Non asbestos-containing 12" x 12" brown floor tile with brown and white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #14 – Non asbestos-containing gray roof shingles

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Amtrak Station Photo Log



HA #15 – Non asbestos-containing 2' x 4' white lay-in ceiling tile  
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Amtrak Station Photo Log



HA #16 – Non asbestos-containing 2' x 4' white textured lay-in ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956