

Van Hoosen Hall Photo Log



Photo 1 – Asbestos-containing spray-on acoustical ceiling plaster (popcorn)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 2 – Non asbestos-containing plaster (smooth)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 3 – Non asbestos-containing 4” black cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 4 – Non asbestos-containing 12” x 12” cream floor tile with white and tan streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 5 – Non asbestos-containing white sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 6 – Asbestos-containing cream linoleum
with mosaic pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Photo 7 – Non asbestos-containing domestic water supply and
return pipe joint and hanger insulation
and
Asbestos-containing domestic water supply and
return pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 8 – Non asbestos-containing 12” x 12” tan linoleum
with swirl pattern and associated mastic
and
Non asbestos-containing 4” cream cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 9 – Non asbestos-containing 4” brown cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 10 – Non asbestos-containing vinyl wood grain flooring
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 11 – Asbestos-containing 9” x 9” beige floor tile with cream and tan streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 12 – Assumed asbestos-containing window
and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 13 – Exterior of VanHoosen Hall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Van Hoosen Hall Photo Log



Photo 14 – Asbestos-containing 9” x 9” dark brown floor tile with cream and rust streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Photo 15 – Asbestos-containing steam/condensate supply and return pipe straight, pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956