

Owen Hall Photo Log



HA #1 – Asbestos-containing steam/condensate supply and return pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #2 – Asbestos-containing steam/condensate supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #3 – Non asbestos-containing canvas wrap on fiberglass pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #4 – Asbestos-containing domestic water supply and return pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #5 – Asbestos-containing hot water holding tank insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #6 – Non asbestos-containing gray HVAC duct caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #7 – Non asbestos-containing ventilation duct expansion cloth

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #8 – Asbestos-containing 9” x 9” black floor tile with cream streaks and associated non asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #9 - Non asbestos-containing 4" black cove molding  
and associated mastic

HA #33 – Non asbestos-containing green flooring with black and white  
specks and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #10 – Non asbestos-containing smooth plaster

HA #15 – Non asbestos-containing 4” brown cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #11 – Non asbestos-containing 12” x 12” white ceiling tile  
with pin holes and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #12 – Non asbestos-containing 18” x 18” green vinyl flooring with cream and black specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #13 – Non asbestos-containing green stair tread with cream and black specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #14 – Non asbestos-containing 12” x 12” white ceiling tile  
with fissures and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #16 – Non asbestos-containing gray vinyl flooring  
with black and white specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #17 – Non asbestos-containing 2' x 2' white drop ceiling tile  
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #18 – Asbestos-containing drain pipe joint and hanger insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #19 – Non asbestos-containing 12” x 12” white ceiling tile  
with pin holes and fissures and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #20 – Non asbestos-containing 12” x 12” light gray floor tile  
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #21 – Non asbestos-containing 4” gray cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Owen Hall Photo Log



HA #22 – Non asbestos-containing 12” x 12” green floor tile  
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #24 – Assumed asbestos-containing chalkboards  
and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #25 – Assumed asbestos-containing window  
and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #26 – Asbestos-containing spray-on acoustical ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #27 – Asbestos-containing 12” x 12” beige floor tile  
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #28 – Asbestos-containing 12” x 12” maroon floor tile  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #29 – Non asbestos-containing 12” x 12” tan floor tile with marble pattern and associated asbestos-containing mastic

HA #30 – Non asbestos-containing 12” x 12” dark green floor tile with marble pattern and associated asbestos-containing mastic

HA #31 – Non asbestos-containing 12” x 12” red floor tile with marble pattern and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #32 – Asbestos-containing 12” x 12” forest green floor tile  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



HA #35 – Non asbestos-containing white sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #36 – Non asbestos-containing tan vinyl flooring  
with mosaic pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #37 – Non asbestos-containing 2' x 2' white lay-in ceiling tile  
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #38 – Non asbestos-containing 2' x 2' white lay-in smooth gypsum board ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #39 – Non asbestos-containing 12” x 12” tan floor tile  
and associated asbestos-containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #40 – Non asbestos-containing 12” x 12” chocolate floor tile  
with yellow and rust streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Owen Hall Photo Log



HA #43 – Assumed asbestos-containing roofing products/materials

For more information contact MSU Environmental Health and Safety – (517) 353-8956