

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



Plant Pathology (#452)

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #1 – Non asbestos containing drywall

HA #2 – Non asbestos containing drywall joint compound

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #3 – Asbestos containing sink and lab bench undercoating

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #4 – Non asbestos containing 4” black cove molding and associated mastic

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #5 – Non asbestos containing white caulk around duct

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #6 – Assumed asbestos containing silver furnace exhaust

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #7 – Non asbestos containing white exterior caulk

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #8 – Assumed asbestos containing fire door and frame

Michigan State University
Botany Field Lab (Plant Pathology) - Asbestos Inspection Photo Log



HA #9 – Assumed asbestos containing roofing caulk