Michigan State University Asbestos Inspection Photo Log



River Water Intake Station (#515)

Michigan State University Asbestos Inspection Photo Log



HA #1 – Assumed Fire Door and Frame

Michigan State University Asbestos Inspection Photo Log



HA #2 – Assumed Roofing Materials and Products