

Food Stores Photo Log



Photo 1 – Assumed asbestos-containing gray building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 2 – Food Stores – exterior of building

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log




Photo 3 – Assumed asbestos-containing gray building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 4 – Assumed asbestos-containing black building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 5 – Assumed asbestos-containing white and black exterior building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 6 – Assumed asbestos-containing black building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 7 – Assumed asbestos-containing green building caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 8 – Non asbestos-containing cream and vinyl flooring  
with tan specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 9 – Non asbestos-containing 4” black cove molding  
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 10 – Non asbestos-containing 12” x 12” cream floor tile with rust streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 11 – Non asbestos-containing 2' x 4' white lay-in ceiling tile with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 12 – Asbestos-containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 13 – Non asbestos-containing drywall

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 14 – Non asbestos-containing 2' x 2' white drop-in ceiling tile with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 15 – Non asbestos-containing cream sink undercoating

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log




Photo 16 – Non asbestos-containing gray refrigeration caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 17 – Non asbestos-containing white refrigeration caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 18 – Non asbestos-containing white interior window frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 19 – Non asbestos-containing plaster over ventilation ductwork

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 20 – Asbestos-containing domestic water pipe joint insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 21 – Non asbestos-containing domestic water pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Food Stores Photo Log



Photo 22 – Asbestos-containing domestic water pipe joint insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956