

Erickson Hall Photo Log



Exterior of Building

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing plaster (smooth)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Assumed asbestos-containing window and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" tan floor tile with white and rust streaks
(mastic is asbestos-containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing ventilation duct expansion cloth

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing cream stair tread with tan specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing cream vinyl flooring with tan specks
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" army green marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" gray marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12” x 12” brown floor tile with cream and green streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12” x 12” cream floor tile with gray and tan marble pattern and associated mastic

Non-asbestos containing 4” gray cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Asbestos-containing red linoleum with white streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Asbestos-containing vinyl stair tread with white streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Asbestos-containing 4" red cove molding with white streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" beige floor tile with cream and green streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" green marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Asbestos-containing 9" x 9" dark brown floor tile with cream and rust streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 4" army green cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" gray marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 4" brown cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956



Asbestos-containing drain system pipe straight insulation

-- and --

Asbestos-containing drain system pipe joint insulation

Erickson Hall Photo Log



Non-asbestos containing tan stair tread with cream and brown streaks
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 12" x 12" tan linoleum squares with cream and brown streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing 2' x 2' tan vinyl flooring with multicolored specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Erickson Hall Photo Log



Non-asbestos containing tan stair tread with multicolored specks
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956