

Photo Log
Michigan State University, Music Building
Asbestos Containing Materials

1. Elevation view of the Music Building.



2. Round Light Fixture Pads, HA# 2



3. Brown Wool Pipe Insulation and Mud Fittings on Brown Wool Pipe Insulation, HA#^s 3 & 4.



Photo Log
Michigan State University, Music Building
Asbestos Containing Materials

4. Mag. Pipe Insulation and Mud Fittings on Mag. Pipe Insulation, HA#'s 7 & 8.



5. Mud Fittings on Fiberglass (Paper) Insulation, HA# 9



6. White HVAC Fabric, HA# 10.



Photo Log
Michigan State University, Music Building
Asbestos Containing Materials

7. 9" x 9" Brown Floor Tile w/ Cream and Red Streaks (Mastic Negative), HA# 11.



8. 9" x 9" Maroon Floor Tile w/ Cream Streaks (Mastic Negative), HA# 12.



9. 9" x 9" Black Floor Tile w/ White Specs (Mastic Negative), HA# 18.



Photo Log
Michigan State University, Music Building
Asbestos Containing Materials

10. 9" x 9" Maroon Floor Tile w/ White Specs (Mastic Negative), HA# 19.



11. 9" x 9" Brown Floor Tile w/ White Specs (Mastic Negative), HA# 20.



12. Tank Insulation, HA# 22.



Photo Log
Michigan State University, Music Building
Asbestos Containing Materials

13. Assumed Tagged Fire Door and Frame, HA# 30.

