


Kellogg Hotel and Conference Center Photo Log




HA #1 – Non asbestos containing drywall

HA #2 – Non asbestos containing drywall joint compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #3 – Non asbestos containing drywall with plaster skim coat

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log




HA #4 – Non asbestos containing dark brown window caulk

HA #23 – Non asbestos containing dark brown window glazing compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log




HA #12 – Non asbestos containing 2” x 2” light brown ceramic floor tile bedding compound

HA #13 – Non asbestos containing 18” x 18” light brown squared ceramic wall tile bedding compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #14 – Non asbestos containing 12” x 12” light brown textured glued-on ceiling tile and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #16 – Asbestos containing 9” x 9” black floor tile with white streaks and associated non asbestos containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #17 – Non asbestos containing black cove molding
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #18 – Non asbestos containing 12” x 12” green floor tile
with white and black streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #19 – Non asbestos containing 2' x 2' light
brown textured drop ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #20 – Asbestos containing red stair tread and associated non asbestos containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #21 – Non asbestos containing red linoleum with white streaks

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #24 – Asbestos containing textured ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log




HA #26 – Assumed asbestos containing black roof flashing

HA #27 – Assumed asbestos containing black roof membrane

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA # 28 – Non asbestos containing 2' x 2' white lined drop ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #29 – Non asbestos containing 12” x 12” red floor tile with white streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #30 – Non asbestos containing white floor tile with blue streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #32 – Non asbestos containing 2' x 2' white lay-in ceiling tile with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #33 – Non asbestos containing 2' x 2' white lay-in ceiling tile with raised 2" x 2" squares

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #34 – Non asbestos containing 2' x 4' white drop in ceiling tile
with pin holes and fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #35 – Non asbestos containing black vibration collar

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #36 – Asbestos containing steam pipe joint insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #42 – Non asbestos containing tan linoleum and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #45 – Non asbestos containing gray duct caulk

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #46 – Asbestos containing 12” x 12” black floor tile with brown streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #47 – Asbestos containing 9” x 9” brown floor tile with brown and white streaks and associated non asbestos containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #48 – Non asbestos containing 4” dark brown
cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #49 – Non asbestos containing 2' x 2' off-white fuzzy drop-in ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #50 – Non asbestos containing 2' x 2' white drop in ceiling tile with pin holes

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #51 – Non asbestos containing 2' x 2' white smooth lay-in ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #52 – Non asbestos containing red ceramic floor
tile with squares bedding compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #53 – Non asbestos containing 12” x 12” beige floor tile
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA # 54 – Non asbestos containing 6” green cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #56 – Non asbestos containing white ceramic wall tile
bedding compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #59 – Non asbestos containing gray circle pattern linoleum

HA #60 – Non asbestos containing gray stair tread and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #61 – Non asbestos containing 4” gray cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #62 – Non asbestos containing 12” x 12” white floor tile with brown and white streaks and associated asbestos containing mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #63 – Non asbestos containing 4” green cove
molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #66 – Non asbestos containing 2' x 2' white drop-in ceiling tile with tiny squares

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #67 – Non asbestos containing 2' x 2' white small textured drop ceiling tile

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #70 – Non asbestos containing 12” x 12” gray floor tile
with marble pattern and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #76 – Non asbestos containing duct insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Kellogg Hotel and Conference Center Photo Log



HA #77 – Asbestos containing tank insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #79 – Non asbestos containing white acoustical ceiling

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Kellogg Hotel and Conference Center Photo Log



HA #80 – Non asbestos containing green linoleum

HA #81 – Non asbestos containing 6” black cove
molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956