


Photo Log
Michigan State University, Center for Integrative Plant Systems
Asbestos Containing Materials

1. Elevation view of the Center for Integrative Plant Systems.



2. Transite Ceiling Panels, HA# 1.



3. Mud Fittings on Fiberglass Pipe Insulation, HA# 2



Photo Log
Michigan State University, Center for Integrative Plant Systems
Asbestos Containing Materials

4. Assumed Transite Lab Table Tops, HA# 7.



5. Assumed Transite Pegboards, HA# 14



6. Electrical Insulation Cloth, HA# 15.



Photo Log
Michigan State University, Center for Integrative Plant Systems
Asbestos Containing Materials

7. Tank Insulation, HA# 16.



8. Mag. Pipe Insulation & Mud Fittings on Mag. Pipe Insulation, HA# 17 &18.



9. 9" x 9" Beige Floor Tile w/ Swirl Pattern (Mastic Negative), HA# 19.



Photo Log
Michigan State University, Center for Integrative Plant Systems
Asbestos Containing Materials

10. Assumed Transite Lab Hoods, HA# 22.



11. Black Sink Undercoating, HA# 24.

