

Abbot Hall Photo Log



Non-asbestos containing decorative ceiling plaster

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 12" x 12" cream marble pattern floor tile
and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Abbot Hall Photo Log



Non-asbestos containing 2' x 2' white lay-in ceiling tile with fissures

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 6" black cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 12" x 12" black floor tile with white specks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 9" x 9" brown floor tile with cream and rust streaks
and associated mastic

Asbestos-containing 9" x 9" dark brown floor tile with cream and rust streaks
and associated mastic

Asbestos-containing 1' x 2' black floor tile and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing steam/condensate supply & return pipe joint insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing steam/condensate supply & return pipe straight insulation

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 12" x 12" brown floor tile and associated mastic
(painted gray in Laundry #7)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 12" x 12" cream floor tile with tan and rust streaks
(mastic is asbestos-containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing white lay-in ceiling tile with pin holes

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 6" brown cove molding and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 12" x 12" white ceiling tile with fissures and associated glue pods

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Assumed asbestos-containing fire door and frame

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing plaster (smooth)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing gray duct caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 9" x 9" cream floor tile with pink and green streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing 12" x 12" gray floor tile with cream streaks (painted black) and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 12" x 12" chocolate brown floor tile with cream streaks and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 9" x 9" chocolate brown floor tile with cream streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 9" x 9" beige floor tile with swirls
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Asbestos-containing 9" x 9" army green floor tile with cream streaks
(mastic is non-asbestos containing)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Assumed asbestos-containing window and door frame caulk compound

For more information contact MSU Environmental Health and Safety – (517) 353-8956


Abbot Hall Photo Log



Non-asbestos containing brown floor covering and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Non-asbestos containing white vinyl floor tile with blue and white chips and associated mastic

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Abbot Hall Photo Log



Front of building

For more information contact MSU Environmental Health and Safety – (517) 353-8956