

Michigan State University
Soil Science Storage - Asbestos Inspection Photo Log



Soil Science Storage Building (#430B)

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Storage - Asbestos Inspection Photo Log



HA #1 – Non-asbestos containing white window glazing

For more information contact MSU Environmental Health and Safety – (517) 353-8956

Michigan State University
Soil Science Storage - Asbestos Inspection Photo Log



HA #2 – Non-asbestos containing gray shingles and associated products

For more information contact MSU Environmental Health and Safety – (517) 353-8956